

October 14, 2013

1

UL 762

POWER ROOF VENTILATORS FOR RESTAURANT EXHAUST APPLIANCES

ISSUE NO: 7

OCTOBER 14, 2013

***Summary of Topics:***

***This revision of Subject 762 is being issued to in order to cover the duct fans of the straight-through type.***

The UL Foreword is no longer located within the UL Outline of Investigation. For information concerning the use and application of the requirements contained in this Outline of Investigation, the current version of the UL Foreword is located on ULStandardsInfoNet at: <http://ulstandardsinfo.net.ul.com/ulforeword.html>

This issue becomes effective October 14, 2013.

COPYRIGHT © 2013 UNDERWRITERS LABORATORIES INC.

No Text on This Page

## CONTENTS

### INTRODUCTION

1 Scope .....	4
2 General .....	4
3 Undated References .....	4

### CONSTRUCTION

4 Assembly .....	4
5 Guarding of Moving Parts .....	5
6 Operation .....	5
7 Duct Connection .....	6

### PERFORMANCE

8 Test Installation for Test No. 1 – Normal Temperature Test .....	6
9 Temperature Measurement and Flue-Gas Generator for Test No. 1 – Normal Temperature Test ..	7
10 Test No. 1 – Normal Temperature Test .....	8
10.1 Method .....	8
10.2 Requirements .....	9
11 Test Installation for Test No. 2 – Abnormal Flare Up Test .....	12
12 Temperature Measurement for Test No. 2 – Abnormal Flare Up Test .....	13
13 Test No. 2 – Abnormal Flare Up Test .....	13
13.1 Method .....	13
13.2 Requirements .....	13
14 Test No. 3 – Accelerated Air-Oven Aging Test .....	13
14.1 General .....	13
14.2 Apparatus .....	14
14.3 Method .....	14
15 Test No. 4 – Immersion Tests of Gaskets and Seals .....	15
15.1 General .....	15
15.2 Apparatus .....	16
15.3 Method .....	16

### INSTRUCTIONS

16 Installation Instructions .....	17
------------------------------------	----