

An ACI Standard

# Specification for Repairing Concrete with Epoxy Mortar

Reported by ACI Committee 548

ACI 548.14-14



American Concrete Institute  
*Always advancing*

This is a preview. [Click here to purchase the full publication.](#)



## Specification for Repairing Concrete with Epoxy Mortar

Copyright by the American Concrete Institute, Farmington Hills, MI. All rights reserved. This material may not be reproduced or copied, in whole or part, in any printed, mechanical, electronic, film, or other distribution and storage media, without the written consent of ACI.

The technical committees responsible for ACI committee reports and standards strive to avoid ambiguities, omissions, and errors in these documents. In spite of these efforts, the users of ACI documents occasionally find information or requirements that may be subject to more than one interpretation or may be incomplete or incorrect. Users who have suggestions for the improvement of ACI documents are requested to contact ACI via the errata website at <http://concrete.org/Publications/DocumentErrata.aspx>. Proper use of this document includes periodically checking for errata for the most up-to-date revisions.

ACI committee documents are intended for the use of individuals who are competent to evaluate the significance and limitations of its content and recommendations and who will accept responsibility for the application of the material it contains. Individuals who use this publication in any way assume all risk and accept total responsibility for the application and use of this information.

All information in this publication is provided “as is” without warranty of any kind, either express or implied, including but not limited to, the implied warranties of merchantability, fitness for a particular purpose or non-infringement.

ACI and its members disclaim liability for damages of any kind, including any special, indirect, incidental, or consequential damages, including without limitation, lost revenues or lost profits, which may result from the use of this publication.

It is the responsibility of the user of this document to establish health and safety practices appropriate to the specific circumstances involved with its use. ACI does not make any representations with regard to health and safety issues and the use of this document. The user must determine the applicability of all regulatory limitations before applying the document and must comply with all applicable laws and regulations, including but not limited to, United States Occupational Safety and Health Administration (OSHA) health and safety standards.

Participation by governmental representatives in the work of the American Concrete Institute and in the development of Institute standards does not constitute governmental endorsement of ACI or the standards that it develops.

Order information: ACI documents are available in print, by download, on CD-ROM, through electronic subscription, or reprint and may be obtained by contacting ACI.

Most ACI standards and committee reports are gathered together in the annually revised ACI Manual of Concrete Practice (MCP).

**American Concrete Institute**  
**38800 Country Club Drive**  
**Farmington Hills, MI 48331**  
**Phone: +1.248.848.3700**  
**Fax: +1.248.848.3701**

[www.concrete.org](http://www.concrete.org)

# Specification for Repairing Concrete with Epoxy Mortar

An ACI Standard

Reported by ACI Committee 548

Bradley Nemunaitis, Chair

Mahmoud M. Reda Taha, Secretary

Ashraf I. Ahmed  
Mohammad A. Alhassan  
Milton D. Anderson  
Jacques A. Bertrand  
Constantin Bodea  
Chris Davis  
David W. Fowler  
Quentin L. Hibben  
Albert O. Kaeding  
John R. Milliron  
Myles A. Murray  
Joseph A. Nuciforo Jr.  
John R. Robinson

Michael L. Schmidt  
Joe Solomon  
Michael M. Sprinkel  
Michael S. Stenko  
Donald P. Tragianese  
Wafeek S. Wahby  
David White  
David P. Whitney  
Richard E. Wollmershauser

*Consulting Members*  
Lu Anqi  
Craig A. Ballinger

John J. Bartholomew  
Shashi P. Bhatnagar  
Zhi-Yuan Chen  
Inz Lech Czarnecki  
Harold (Dan) R. Edwards  
Larry J. Farrell  
Jack J. Fontana  
George Horeczko  
David P. Hu  
Bert Paw Kriekemans  
Deon Kruger  
William Lee  
Troy D. Madeley

Henry N. Marsh Jr.  
Peter Mendis  
Peter J. Moss  
Yoshihiko Ohama  
Kelly M. Page  
Jerzy Pietrzykowski  
Hamid Saadatmanesh  
Donald A. Schmidt  
Meyer Steinberg  
Harold H. Weber Jr.

*This specification describes the work of repairing defects in hardened portland-cement concrete with an epoxy mortar. Included are controls for epoxy resin system labeling, storage, handling, surface evaluation and preparation, mixing and application, inspection, quality control, and testing.*

**Keywords:** adhesion to concrete; aggregate; concrete construction; epoxy; hardened concrete; epoxy mortar; quality control; repairs; resurfacing.

3.3—Epoxy mortar mixtures, p. 3  
3.4—Epoxy mortar application, p. 3  
3.5—Field quality control, p. 3  
3.6—Cleanup, p. 3  
3.7—Safety, p. 4

*(nonmandatory portion follows)*

## CONTENTS

*(mandatory portion follows)*

### PART 1—GENERAL, p. 2

- 1.1—Scope, p. 2
- 1.2—Interpretation, p. 2
- 1.3—Definitions, p. 2
- 1.4—Referenced standards, p. 2
- 1.5—Submittals, p. 2
- 1.6—Product delivery, storage, and handling, p. 2
- 1.7—Project conditions, p. 3

### PART 2—PRODUCTS, p. 3

- 2.1—Materials, p. 3

### PART 3—EXECUTION, p. 3

- 3.1—Preparation, p. 3
- 3.2—Inspection of surface prior to epoxy mortar application, p. 3

### NOTES TO SPECIFIER, p. 4

General notes, p. 4

### FOREWORD TO CHECKLISTS, p. 4

### MANDATORY REQUIREMENTS CHECKLIST, p. 5

### OPTIONAL REQUIREMENTS CHECKLIST, p. 5

*(mandatory portion follows)*

ACI 548.14-14 was adopted December 18, 2014 and published February 2015.

Copyright © 2014, American Concrete Institute.

All rights reserved including rights of reproduction and use in any form or by any means, including the making of copies by any photo process, or by electronic or mechanical device, printed, written, or oral, or recording for sound or visual reproduction or for use in any knowledge or retrieval system or device, unless permission in writing is granted by the American Concrete Institute.

This is a preview. Click here to purchase the full publication.

