

An ACI Standard

Specification for Repairing Concrete with Epoxy Mortar

Reported by ACI Committee 548

ACI 548.14M-14



American Concrete Institute
Always advancing

This is a preview. [Click here to purchase the full publication.](#)



Specification for Repairing Concrete with Epoxy Mortar

Copyright by the American Concrete Institute, Farmington Hills, MI. All rights reserved. This material may not be reproduced or copied, in whole or part, in any printed, mechanical, electronic, film, or other distribution and storage media, without the written consent of ACI.

The technical committees responsible for ACI committee reports and standards strive to avoid ambiguities, omissions, and errors in these documents. In spite of these efforts, the users of ACI documents occasionally find information or requirements that may be subject to more than one interpretation or may be incomplete or incorrect. Users who have suggestions for the improvement of ACI documents are requested to contact ACI via the errata website at <http://concrete.org/Publications/DocumentErrata.aspx>. Proper use of this document includes periodically checking for errata for the most up-to-date revisions.

ACI committee documents are intended for the use of individuals who are competent to evaluate the significance and limitations of its content and recommendations and who will accept responsibility for the application of the material it contains. Individuals who use this publication in any way assume all risk and accept total responsibility for the application and use of this information.

All information in this publication is provided “as is” without warranty of any kind, either express or implied, including but not limited to, the implied warranties of merchantability, fitness for a particular purpose or non-infringement.

ACI and its members disclaim liability for damages of any kind, including any special, indirect, incidental, or consequential damages, including without limitation, lost revenues or lost profits, which may result from the use of this publication.

It is the responsibility of the user of this document to establish health and safety practices appropriate to the specific circumstances involved with its use. ACI does not make any representations with regard to health and safety issues and the use of this document. The user must determine the applicability of all regulatory limitations before applying the document and must comply with all applicable laws and regulations, including but not limited to, United States Occupational Safety and Health Administration (OSHA) health and safety standards.

Participation by governmental representatives in the work of the American Concrete Institute and in the development of Institute standards does not constitute governmental endorsement of ACI or the standards that it develops.

Order information: ACI documents are available in print, by download, on CD-ROM, through electronic subscription, or reprint and may be obtained by contacting ACI.

Most ACI standards and committee reports are gathered together in the annually revised ACI Manual of Concrete Practice (MCP).

American Concrete Institute
38800 Country Club Drive
Farmington Hills, MI 48331
Phone: +1.248.848.3700
Fax: +1.248.848.3701

www.concrete.org

Specification for Repairing Concrete with Epoxy Mortar

An ACI Standard

Reported by ACI Committee 548

Bradley Nemunaitis, Chair

Mahmoud M. Reda Taha, Secretary

Ashraf I. Ahmed
Mohammad A. Alhassan
Milton D. Anderson
Jacques A. Bertrand
Constantin Bodea
Chris Davis
David W. Fowler
Quentin L. Hibben
Albert O. Kaeding
John R. Milliron
Myles A. Murray
Joseph A. Nuciforo Jr.
John R. Robinson

Michael L. Schmidt
Joe Solomon
Michael M. Sprinkel
Michael S. Stenko
Donald P. Tragianese
Wafeek S. Wahby
David White
David P. Whitney
Richard E. Wollmershauser

Consulting Members
Lu Anqi
Craig A. Ballinger

John J. Bartholomew
Shashi P. Bhatnagar
Zhi-Yuan Chen
Inz Lech Czarnecki
Harold (Dan) R. Edwards
Larry J. Farrell
Jack J. Fontana
George Horeczko
David P. Hu
Bert Paw Kriekemans
Deon Kruger
William Lee
Troy D. Madeley

Henry N. Marsh Jr.
Peter Mendis
Peter J. Moss
Yoshihiko Ohama
Kelly M. Page
Jerzy Pietrzykowski
Hamid Saadatmanesh
Donald A. Schmidt
Meyer Steinberg
Harold H. Weber Jr.

The official version of this ACI document uses inch-pound units. A conversion of an ACI document into SI units is for the convenience of users. Care has been taken to ensure that the conversion is correct; however, ACI does not guarantee its accuracy. Official interpretation of this ACI document shall be based only on the U.S. customary units.

This specification describes the work of repairing defects in hardened portland-cement concrete with an epoxy mortar. Included are controls for epoxy resin system labeling, storage, handling, surface evaluation and preparation, mixing and application, inspection, quality control, and testing.

Keywords: adhesion to concrete; aggregate; concrete construction; epoxy; epoxy mortar; hardened concrete; quality control; repairs; resurfacing.

CONTENTS

(mandatory portion follows)

PART 1—GENERAL, p. 2

- 1.1—Scope, p. 2
- 1.2—Interpretation, p. 2
- 1.3—Definitions, p. 2
- 1.4—Referenced standards, p. 2
- 1.5—Submittals, p. 2
- 1.6—Product delivery, storage, and handling, p. 2
- 1.7—Project conditions, p. 3

PART 2—PRODUCTS, p. 3

- 2.1—Materials, p. 3

PART 3—EXECUTION, p. 3

- 3.1—Preparation, p. 3
- 3.2—Inspection of surface prior to epoxy mortar application, p. 3
- 3.3—Epoxy mortar mixtures, p. 3
- 3.4—Epoxy mortar application, p. 3
- 3.5—Field quality control, p. 3
- 3.6—Cleanup, p. 3
- 3.7—Safety, p. 4

(nonmandatory portion follows)

NOTES TO SPECIFIER, p. 4

- General notes, p. 4

ACI 548.14M-14 was adopted December 18, 2014 and published May 2015.

Copyright © 2015, American Concrete Institute.

All rights reserved including rights of reproduction and use in any form or by any means, including the making of copies by any photo process, or by electronic or mechanical device, printed, written, or oral, or recording for sound or visual reproduction or for use in any knowledge or retrieval system or device, unless permission in writing is granted by the American Concrete Institute.

This is a preview. Click here to purchase the full publication.

